

# 境川橋震害圖

## ELEVATION & PLAN OF SAKAIGAWA

Showing the condition after the earthquake disaster of Oct. 28th,  
All the piers, each consisting of a couple of cast iron screw piles, 2'6" in diameter and filled with concrete, broken

Scale 10 ft. = 1 inch.

境川橋震害圖(其一)

