

捐斐川橋震害圖
 ELEVATION AND PLAN
 OF
 IBIGAWA BRIDGE.

Showing the condition after the earthquake disaster of Oct. 28th, 1891.
 All the piers, each consisting of a pair of brick columns, 12' in diameter, broken a few feet above low water level and displaced a few inches in various directions.
 The west abutment settled down 1 foot and badly cracked.
 Scale: 20 ft. to an inch.

