

橋震害圖

度
呎拾貳爲
SIDE AND FR
OF
KISOGAWA

木曾川橋震害圖(其二)

Showing the condition after the earth
All piers and abutments cracked at a few feet ab
less displaced in var
Scale: 20 ft. to

