

圖脚橋造改及圖害震橋川犀  
 ELEVATION OF SAIGAWA BRIDGE.

Showing  
 The condition after the earthquake disaster of Oct. 28th, 1891.

Scale 5 ft. = 1 inch.

犀川橋震害圖及改造橋脚圖(其一)

